



If your **CHASE COVER** is in this condition, it indicates that your fireplace is not being maintained. Most fireplaces that have to be replaced are caused by this condition existing. Water may be penetrating the **STORM COLLAR** and running down the flue and rusting the top of your fireplace. When this happens the only solution is removing the whole fireplace, fireplace surround (marble, brick, etc.) and the flue. The cost of this ranges from \$3,500 and up. This condition also is a fire hazard and also can cause smoke damage to your home. Be prudent and call us and possibly replace the chase cover and storm collar only.

*East Coast Fireplace
& Chimney Sweeps, Inc.*



Call Today

732-792-0300

Senior Citizen Discount

Lic.#13VH02050700

\$10 OFF

**DRYER VENT
CLEANING**

WITH THIS COUPON

\$10⁰⁰ OFF

**ANY FURNACE,
FIREPLACE OR
WOODSTOVE CLEANING**

With this coupon

\$25⁰⁰ OFF

**ANY COMBINATION
OF 2 CLEANINGS
(ONE HOUSEHOLD)**

With this coupon

\$10⁰⁰ OFF

ANY GAS SERVICING

- GAS LOGS
- DIRECT VENT FIREPLACE
- VENT FREE FIREPLACE

With this coupon

\$10⁰⁰ OFF

**CHIMNEY FLUE
CAP INSTALLED**

Provides Protection Against Squirrels,
Raccoons, Birds, Bats, Leaves, Rain,
Sparks, Roof Fires

With this coupon